NATIONAL SPHERICAL TORUS EXPERIMENT
UPGRADE PROJECT
Engineering Change Proposal (ECP)

Part I To be Completed by Originator

Main Menu
Log
Print PDF

ECP-019

COVER PAGE

Originator (CAM) Perry

Date Submitted 02/17/2012

ECP Title Move tasks for drilling additional holes in outer TF flags (tasks 1301-0300 and 1301-0310) from Control Account 1301 to Control Account 8200

ECP No. 019

Required Reviewers (Change Control Board) Williams Langish Strykowsky Other... Dudek Stevenson Change Level 3 Project Manager

Approvals

Change Level	Approving Official	Approval	Signature
3	NSTXU Project Manager	□Yes □No	
3a Expedited ECP	NSTXU Engineering Lead	□Yes □No	
2	NSTXU Federal Project Dir.	□Yes □No	
1	Associated Director OFES	□Yes □No	
0	Deputy Secretary of Energy	□Yes □No	

Approval Date

Primavera Updated Cobra Updated

. WAD Updated

RAM Updated



NATIONAL SPHERICAL TORUS EXPERIMENT UPGRADE PROJECT Engineering Change Proposal (ECP) Part I To be Completed by Originator

Main Menu		
Log		
Print PDF		

ECP-019

PART I					
Originator (CAM)	Perry	Date Submitted 02/17/2012			
Type of ECP	Standard Expedited				
Type of Change (Check all that apply)	Type of Change (Check all that apply) Technical Cost Schedule Editorial Other				
Reason for Change		in outer TF flags (tasks 1301-0300 and 1301 control Account 8200 since this work will be 8200 scope.			
Impacted WBS Elements	 □ 1.1 □ 1.2 □ 1.3 □ 1.4 □ 1.5 □ 1.6 □ 1.7 ☑ 1.8 □ Other 				
Control Account	□ 1000 □ 1306 □ 2470 □ 5000 ⊠ 82 □ 1001 □ 1307 □ 2475 □ 5200 □ 82 □ 1002 □ 1310 □ 2480 □ 5501 □ 82 □ 1200 □ 2300 □ 2485 □ 6100 □ Ot □ 1300 □ 2420 □ 2490 □ 7200 ⊠ 1301 □ 2425 □ 3200 □ 7300 □ 1302 □ 2430 □ 3300 □ 7400 □ 1303 □ 2440 □ 3400 □ 7100 □ 1304 □ 2450 □ 4100 □ 7710 □ 1305 □ 2460 □ 4500 □ 7900	10 50			
Impacts of Change (Briefly Describe)	None Simplifies time collection for field technicia	ns performing the work.			
Impact on Materials Parts Already Manuf. If yes, what is recommended disposition					

NATIONAL SPHERICAL TORUS EXPERIMENT UPGRADE PROJECT Engineering Change Proposal (ECP) Part I To be Completed by Originator

Main Menu		
Log		
Print PDF		

ECP-019

Detailed Description of Change

Description of Change do to job 8200 since this work will be performed by the field technicians performing the 8200 scope.

SUBMIT ECP

Do not fill in information below this point

List of Primavera Schedule (Before/After) Cobra (Before/After) Other... Attachments